

HABS
NC
84-ALB
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to
Freeman-Marks House
112 North Third Street
Albemarle
Stanley County
North Carolina

HABS No. NC-237

Jack E. Boucher, Photographer, May 1978

- NC-237-1 EXTERIOR, SOUTH FRONT
- NC-237-2 EXTERIOR, NORTH REAR
- NC-237-3 EXTERIOR, EAST SIDE
- NC-237-4 EXTERIOR, WEST SIDE
- NC-237-5 EXTERIOR, CORNER VIEW, WEST SIDE AND SOUTH FRONT
- NC-237-6 EXTERIOR, CORNER VIEW, SOUTH FRONT AND EAST SIDE
- NC-237-7 EXTERIOR, SOUTH FRONT, ENTRANCE, DOOR
- NC-237-8 EXTERIOR, EAST END OF NORTH SIDE
- NC-237-9 EXTERIOR, EAST SIDE, WINDOW
- NC-237-10 EXTERIOR, DETAIL OF HAND HEWN GIRDER SHOWING MORTAR JOINTS AND
HAND CARVED NUMBERS
- NC-237-11 EXTERIOR, SOUTHWEST CORNER, CORNICE DETAIL
- NC-237-12 INTERIOR, SOUTHWEST ROOM, EAST WALL
- NC-237-13 INTERIOR, SOUTHWEST ROOM, SOUTH WALL
- NC-237-14 INTERIOR, SOUTHWEST ROOM NORTH WALL
- NC-237-15 INTERIOR, SOUTHWEST ROOM, WEST WALL
- NC-237-16 INTERIOR, SOUTHWEST ROOM, WEST WALL, DETAIL OF HAND CARVED MANTEL
- NC-237-17 INTERIOR, SOUTHWEST ROOM, WEST WALL, DETAIL OF SECTION OF
HAND CARVED MANTEL
- NC-237-18 INTERIOR, SOUTHWEST ROOM, WEST WALL, DETAIL OF UPPER PORTION
OF HAND CARVED MANTEL
- NC-237-19 INTERIOR, SOUTHWEST ROOM, WEST WALL, WINDOW ON LEFT SIDE OF MANTEL

NC-237-20	INTERIOR, SOUTHWEST ROOM, EAST WALL, DOOR AND FRAME
NC-237-21	INTERIOR, NORTH END OF NORTH WALL
NC-237-22	INTERIOR, ATTIC, DETAIL OF BEARING WALL BETWEEN SOUTH AND NORTH SIDES OF BUILDING
NC-237-23	INTERIOR, NORTHEAST ROOM EAST ROOM
NC-237-24	INTERIOR, NORTHWEST ROOM, LOOKING NORTHWEST
NC-237-25	INTERIOR, SOUTHEAST ROOM, EAST WALL
NC-237-26	INTERIOR, SOUTHEAST ROOM, LOOKING SOUTH
NC-237-27	INTERIOR, SOUTHEAST ROOM, EAST WALL, MANTEL
NC-237-28	INTERIOR, SOUTHEAST ROOM, LOOKING NORTH
NC-237-29	INTERIOR, DETAIL OF DOOR BETWEEN NORTH HALL & SOUTHWEST ROOM
NC-237-30	INTERIOR, LOOKING FROM NORTHWEST ROOM TO NORTH HALL